UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office ASSISTANT SECRETARY OF COMMERCE AND COMMISSIONER OF PATENTS AND TRADEMARKS

P.O. Box 1450 Alexandria, VA 22313-1450

February 18, 2009

EMRICH AND DITHMAR 300 SOUTH WACKER DRIVE SUITE 3000 CHICAGO IL 60606

Patent No.

: 6,032,898

Inventor(s)

Kenneth H. LaCount, et al.

Issued

: March 7, 2000

For

MULTIPLE ROLL TOWEL

DISPENSER

Doc. No.

1

To Whom It May Concern:

The Certificate of Correction issued on <u>February 17, 2009</u>, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

The title page displaying the corrected illustrative figure was not included in the issued cofc. A superseding cofc will be prepared to include the title page displaying the correct illustrative figure.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson (703) 308-9390 ext. 111 For Mary F. Diggs, Supervisor Decisions & Certificates of Correction Branch (703) 305-8309 / 703-308-9390 ext. 125